1.) Identify the contradiction **Parameters**
2.) Use the **Principles** indicated to generate solutions

Innomation LLC
Atlshuller's Contradiction Matrix

InnomationLLC.com — public domain — Worsening Parameter → / Improving Parameter ↓

#	Improving Parameter	1 Weight of moving object	2 Weight of stationary object	3 Length of moving object	4 Length of stationary object	5 Area of moving object	6 Area of stationary object	7 Volume of moving object	8 Volume of stationary object	9 Speed	10 Force (Intensity)	11 Stress or pressure	12 Shape	13 Stability of the object's composition
1	Weight of moving object	X	-	15, 8, 29,34	-	29, 17, 38, 34	-	29, 2, 40, 28	-	2, 8, 15, 38	8, 10, 18, 37	10, 36, 37, 40	10, 14, 35, 40	1, 35, 19, 39
2	Weight of stationary object	-	X	-	10, 1, 29, 35	-	35, 30, 13, 2	-	5, 35, 14, 2	-	8, 10, 19, 35	13, 29, 10, 18	13, 10, 29, 14	26, 39, 1, 40
3	Length of moving object	8, 15, 29, 34	-	X	-	15, 17, 4	-	7, 17, 4, 35	-	13, 4, 8	17, 10, 4	1, 8, 35	1, 8, 10, 29	1, 8, 15, 34
4	Length of stationary object		35, 28, 40, 29	-	X	-	17, 7, 10, 40	-	35, 8, 2,14	-	28, 10	1, 14, 35	13, 14, 15, 7	39, 37, 35
5	Area of moving object	2, 17, 29, 4	-	14, 15, 18, 4	-	X	-	7, 14, 17, 4		29, 30, 4, 34	19, 30, 35, 2	10, 15, 36, 28	5, 34, 29, 4	11, 2, 13, 39
6	Area of stationary object	-	30, 2, 14, 18	-	26, 7, 9, 39	-	X	-		-	1, 18, 35, 36	10, 15, 36, 37		2, 38
7	Volume of moving object	2, 26, 29, 40	-	1, 7, 4, 35	-	1, 7, 4, 17	-	X	-	29, 4, 38, 34	15, 35, 36, 37	6, 35, 36, 37	1, 15, 29, 4	28, 10, 1, 39
8	Volume of stationary object	-	35, 10, 19, 14	19, 14	35, 8, 2, 14	-		-	X	-	2, 18, 37	24, 35	7, 2, 35	34, 28, 35, 40
9	Speed	2, 28, 13, 38	-	13, 14, 8	-	29, 30, 34	-	7, 29, 34	-	X	13, 28, 15, 19	6, 18, 38, 40	35, 15, 18, 34	28, 33, 1, 18
10	Force (Intensity)	8, 1, 37, 18	18, 13, 1, 28	17, 19, 9, 36	28, 10	19, 10, 15	1, 18, 36, 37	15, 9, 12, 37	2, 36, 18, 37	13, 28, 15, 12	X	18, 21, 11	10, 35, 40, 34	35, 10, 21
11	Stress or pressure	10, 36, 37, 40	13, 29, 10, 18	35, 10, 36	35, 1, 14, 16	10, 15, 36, 28	10, 15, 36, 37	6, 35, 10	35, 24	6, 35, 36	36, 35, 21	X	35, 4, 15, 10	35, 33, 2, 40
12	Shape	8, 10, 29, 40	15, 10, 26, 3	29, 34, 5, 4	13, 14, 10, 7	5, 34, 4, 10		14, 4, 15, 22	7, 2, 35	35, 15, 34, 18	35, 10, 37, 40	34, 15, 10, 14	X	33, 1, 18, 4
13	Stability of the object's composition	21, 35, 2, 39	26, 39, 1, 40	13, 15, 1, 28	37	2, 11, 13	39	28, 10, 19, 39	34, 28, 35, 40	33, 15, 28, 18	10, 35, 21, 16	2, 35, 40	22, 1, 18, 4	X
14	Strength	1, 8, 40, 15	40, 26, 27, 1	1, 15, 8, 35	15, 14, 28, 26	3, 34, 40, 29	9, 40, 28	10, 15, 14, 7	9, 14, 17, 15	8, 13, 26, 14	10, 18, 3, 14	10, 3, 18, 40	10, 30, 35, 40	13, 17, 35
15	Duration of action of moving object	19, 5, 34, 31	-	2, 19, 9	-	3, 17, 19	-	10, 2, 19, 30	-	3, 35, 5	19, 2, 16	19, 3, 27	14, 26, 28, 25	13, 3, 35
16	Duration of action of stationary object	-	6, 27, 19, 16	-	1, 40, 35	-		-	35, 34, 38	-				39, 3, 35, 23
17	Temperature	36,22, 6, 38	22, 35, 32	15, 19, 9	15, 19, 9	3, 35, 39, 18	35, 38	34, 39, 40, 18	35, 6, 4	2, 28, 36, 30	35, 10, 3, 21	35, 39, 19, 2	14, 22, 19, 32	1, 35, 32
18	Illumination intensity	19, 1, 32	2, 35, 32	19, 32, 16		19, 32, 26		2, 13, 10		10, 13, 19	26, 19, 6		32, 30	32, 3, 27
19	Use of energy by moving object	12,18,28,31	-	12, 28	-	15, 19, 25	-	35, 13, 18	-	8, 35, 35	16, 26, 21, 2	23, 14, 25	12, 2, 29	19, 13, 17, 24
20	Use of energy by stationary object	-	19, 9, 6, 27	-		-		-		-	36, 37			27, 4, 29, 18
21	Power	8, 36, 38, 31	19, 26, 17, 27	1, 10, 35, 37		19, 38	17, 32, 13, 38	35, 6, 38	30, 6, 25	15, 35, 2	26, 2, 36, 35	22, 10, 35	29, 14, 2, 40	35, 32, 15, 31
22	Loss of Energy	15, 6, 19, 28	19, 6, 18, 9	7, 2, 6, 13	6, 38, 7	15, 26, 17, 30	17, 7, 30, 18	7, 18, 23	7	16, 35, 38	36, 38			14, 2, 39, 6
23	Loss of Substance	35, 6, 23, 40	35, 6, 22, 32	14, 29, 10, 39	10, 28,24	35, 2, 10, 31	10, 18, 39, 31	1, 29, 30, 36	3, 39, 18, 31	10, 13, 28, 38	14, 15, 18, 40	3, 36, 37, 10	29, 35, 3, 5	2, 14, 30, 40
24	Loss of Information	10, 24, 35	10, 35, 5	1, 26	26	30, 26	30, 16		2, 22	26, 32				
25	Loss of Time	10, 20, 37, 35	10, 20, 26, 5	15, 2, 29	30, 24, 14, 5	26, 4, 5, 16	10, 35, 17, 4	2, 5, 34, 10	35, 16, 32, 18		10, 37, 36,5	37, 36,4	4, 10, 34, 17	35, 3, 22, 5
26	Quantity of substance	35, 6, 18, 31	27, 26, 18, 35	29, 14, 35, 18		15, 14, 29	2, 18, 40, 4	15, 20, 29		35, 29, 34, 28	35, 14, 3	10, 36, 14, 3	35, 14	15, 2, 17, 40
27	Reliability	3, 8, 10, 40	3, 10, 8, 28	15, 9, 14, 4	15, 29, 28, 11	17, 10, 14, 16	32, 35, 40, 4	3, 10, 14, 24	2, 35, 24	21, 35, 11, 28	8, 28, 10, 3	10, 24, 35, 19	35, 1, 16, 11	
28	Measurement accuracy	32, 35, 26, 28	28, 35, 25, 26	28, 26, 5, 16	32, 28, 3, 16	26, 28, 32, 3	26, 28, 32, 3	32, 13, 6		28, 13, 32, 24	32, 2	6, 28, 32	6, 28, 32	32, 35, 13
29	Manufacturing precision	28, 32, 13, 18	28, 35, 27, 9	10, 28, 29, 37	2, 32, 10	28, 33, 29, 32	2, 29, 18, 36	32, 23, 2	25, 10, 35	10, 28, 32	28, 19, 34, 36	3, 35	32, 30, 40	30, 18
30	Object-affected harmful factors	22, 21, 27, 39	2, 22, 13, 24	17, 1, 39, 4	1, 18	22, 1, 33, 28	27, 2, 39, 35	22, 23, 37, 35	34, 39, 19, 27	21, 22, 35, 28	13, 35, 39, 18	22, 2, 37	22, 1, 3, 35	35, 24, 30, 18
31	Object-generated harmful factors	19, 22, 15, 39	35, 22, 1, 39	17, 15, 16, 22		17, 2, 18, 39	22, 1, 40	17, 2, 40	30, 18, 35, 4	35, 28, 3, 23	35, 28, 1, 40	2, 33, 27, 18	35, 1	35, 40, 27, 39
32	Ease of manufacture	28, 29, 15, 16	1, 27, 36, 13	1, 29, 13, 17	15, 17, 27	13, 1, 26, 12	16, 40	13, 29, 1, 40	35	35, 13, 8, 1	35, 12	35, 19, 1, 37	1, 28, 13, 27	11, 13, 1
33	Ease of operation	25, 2, 13, 15	6, 13, 1, 25	1, 17, 13, 12		1, 17, 13, 16	18, 16, 15, 39	1, 16, 35, 15	4, 18, 39, 31	18, 13, 34	28, 13 35	2, 32, 12	15, 34, 29, 28	32, 35, 30
34	Ease of repair	2, 27 35, 11	2, 27, 35, 11	1, 28, 10, 25	3, 18, 31	15, 13, 32	16, 25	25, 2, 35, 11	1	34, 9	1, 11, 10	13	1, 13, 2, 4	2, 35
35	Adaptability or versatility	1, 6, 15, 8	19, 15, 29, 16	35, 1, 29, 2	1, 35, 16	35, 30, 29, 7	15, 16	15, 35, 29		35, 10, 14	15, 17, 20	35, 16	15, 37, 1, 8	35, 30, 14
36	Device complexity	26, 30, 34, 36	2, 26, 35, 39	1, 19, 26, 24	26	14, 1, 13, 16	6, 36	34, 26, 6	1, 16	34, 10, 28	26, 16	19, 1, 35	29, 13, 28, 15	2, 22, 17, 19
37	Difficulty of detecting and measuring	27, 26, 28, 13	6, 13, 28, 1	16, 17, 26, 24	26	2, 13, 18, 17	2, 39, 30, 16	29, 1, 4, 16	2, 18, 26, 31	3, 4, 16, 35	30, 28, 40, 19	35, 36, 37, 32	27, 13, 1, 39	11, 22, 39, 30
38	Extent of automation	28, 26, 18, 35	28, 26, 35, 10	14, 13, 17, 28	23	17, 14, 13		35, 13, 16		28, 10	2, 35	13, 35	15, 32, 1, 13	18, 1
39	Productivity	35, 26, 24, 37	28, 27, 15, 3	18, 4, 28, 38	30, 7, 14, 26	10, 26, 34, 31	10, 35, 17, 7	2, 6, 34, 10	35, 37, 10, 2		28, 15, 10, 36	10, 37, 14	14, 10, 34, 40	35, 3, 22, 39

#	Improving Parameter	14 Strength	15 Duration of action of moving object	16 Duration of action of stationary object	17 Temperature	18 Illumination intensity	19 Use of energy by moving object	20 Use of energy by stationary object	21 Power	22 Loss of Energy	23 Loss of Substance	24 Loss of Information	25 Loss of Time	26 Quantity of substance
1	Weight of moving object	28, 27, 18, 40	5, 34, 31, 35	-	6, 29, 4, 38	19, 1, 32	35, 12, 34, 31	-	12, 36, 18, 31	6, 2, 34, 19	5, 35, 3, 31	10, 24, 35	10, 35, 20, 28	3, 26, 18, 31
2	Weight of stationary object	28, 2, 10, 27	-	2, 27, 19, 6	28, 19, 32, 22	19, 32, 35	-	18, 19, 28, 1	15, 19, 18, 15	18, 19, 28, 15	5, 8, 13, 30	10, 15, 35	10, 20, 35, 26	19, 6, 18, 26
3	Length of moving object	8, 35, 29, 34	19	-	10, 15, 19	32	8, 35, 24	-	1, 35	7, 2, 35, 39	4, 29, 23, 10	1, 24	15, 2, 29	29, 35
4	Length of stationary object	15, 14, 28, 26	-	1, 10, 35	3, 35, 38, 18	3, 25	-		12, 8	6, 28	10, 28, 24, 35	24, 26,	30, 29, 14	
5	Area of moving object	3, 15, 40, 14	6, 3	-	2, 15, 16	15, 32, 19, 13	19, 32	-	19, 10, 32, 18	15, 17, 30, 26	10, 35, 2, 39	30, 26	26, 4	29, 30, 6, 13
6	Area of stationary object	40	-	2, 10, 19, 30	35, 39, 38		-		17, 32	17, 7, 30	10, 14, 18, 39	30, 16	10, 35, 4, 18	2, 18, 40, 4
7	Volume of moving object	9, 14, 15, 7	6, 35, 4	-	34, 39, 10, 18	2, 13, 10	35	-	35, 6, 13, 18	7, 15, 13, 16	36, 39, 34, 10	2, 22	2, 6, 34, 10	29, 30, 7
8	Volume of stationary object	9, 14, 17, 15	-	35, 34, 38	35, 6, 4		-		30, 6		10, 39, 35, 34		35, 16, 32 18	35, 3
9	Speed	8, 3, 26, 14	3, 19, 35, 5	-	28, 30, 36, 2	10, 13, 19	8, 15, 35, 38	-	19, 35, 38, 2	14, 20, 19, 35	10, 13, 28, 38	13, 26		10, 19, 29, 38
10	Force (Intensity)	35, 10, 14, 27	19, 2		35, 10, 21	-	19, 17, 10	1, 16, 36, 37	19, 35, 18, 37	14, 15	8, 35, 40, 5		10, 37, 36	14, 29, 18, 36
11	Stress or pressure	9, 18, 3, 40	19, 3, 27		35, 39, 19, 2	-	14, 24, 10, 37		10, 35, 14	2, 36, 25	10, 36, 3, 37		37, 36, 4	10, 14, 36
12	Shape	30, 14, 10, 40	14, 26, 9, 25		22, 14, 19, 32	13, 15, 32	2, 6, 34, 14		4, 6, 2	14	35, 29, 3, 5		14, 10, 34, 17	36, 22
13	Stability of the object's composition	17, 9, 15	13, 27, 10, 35	39, 3, 35, 23	35, 1, 32	32, 3, 27, 16	13, 19	27, 4, 29, 18	32, 35, 27, 31	14, 2, 39, 6	2, 14, 30, 40		35, 27	15, 32, 35
14	Strength	X	27, 3, 26		30, 10, 40	35, 19	19, 35, 10	35	10, 26, 35, 28	35	35, 28, 31, 40		29, 3, 28, 10	29, 10, 27
15	Duration of action of moving object	27, 3, 10	X	-	19, 35, 39	2, 19, 4, 35	28, 6, 35, 18		19, 10, 35, 38		28, 27, 3, 18	10	20, 10, 28, 18	3, 35, 10, 40
16	Duration of action of stationary object		-	X	19, 18, 36, 40		-		16		27, 16, 18, 38	10	28, 20, 10, 16	3, 35, 31
17	Temperature	10, 30, 22, 40	19, 13, 39	19, 18, 36, 40	X	32, 30, 21, 16	19, 15, 3, 17		2, 14, 17, 25	21, 17, 35, 38	21, 36, 29, 31		35, 28, 21, 18	3, 17, 30, 39
18	Illumination intensity	35, 19	2, 19, 6		32, 35, 19	X	32, 1, 19	32, 35, 1, 15	32	13, 16, 1, 6	13, 1	1, 6	19, 1, 26, 17	1, 19
19	Use of energy by moving object	5, 19, 9, 35	28, 35, 6, 18	-	19, 24, 3, 14	2, 15, 19	X	-	6, 19, 37, 18	12, 22, 15, 24	35, 24, 18, 5		35, 38, 19, 18	34, 23, 16, 18
20	Use of energy by stationary object	35				19, 2, 35, 32	-	X			28, 27, 18, 31			3, 35, 31
21	Power	26, 10, 28	19, 35, 10, 38	16	2, 14, 17, 25	16, 6, 19	16, 6, 19, 37		X	10, 35, 38	28, 27, 18, 38	10, 19	35, 20, 10, 6	4, 34, 19
22	Loss of Energy	26			19, 38, 7	1, 13, 32, 15			3, 38	X	35, 27, 2, 37	19, 10	10, 18, 32, 7	7, 18, 25
23	Loss of Substance	35, 28, 31, 40	28, 27, 3, 18	27, 16, 18, 38	21, 36, 39, 31	1, 6, 13	35, 18, 24, 5	28, 27, 12, 31	28, 27, 18, 38	35, 27, 2, 31	X		15, 18, 35, 10	6, 3, 10, 24
24	Loss of Information		10	10		19			10, 19	19, 10		X	24, 26, 28, 32	24, 28, 35
25	Loss of Time	29, 3, 28, 18	20, 10, 28, 18	28, 20, 10, 16	35, 29, 21, 18	1, 19, 26, 17	35, 38, 19, 18	1	35, 20, 10, 6	10, 5, 18, 32	35, 18, 10, 39	24, 26, 28, 32	X	35, 38, 18, 16
26	Quantity of substance	14, 35, 34, 10	3, 35, 10, 40	3, 35, 31	3, 17, 39		34, 29, 16, 18	3, 35, 31	35	7, 18, 25	6, 3, 10, 24	24, 28, 35	35, 38, 18, 16	X
27	Reliability	11, 28	2, 35, 3, 25	34, 27, 6, 40	3, 35, 10	11, 32, 13	21, 11, 27, 19	36, 23	21, 11, 26, 31	10, 11, 35	10, 35, 29, 39	10, 28	10, 30, 4	21, 28, 40, 3
28	Measurement accuracy	28, 6, 32	28, 6, 32	10, 26, 24	6, 19, 28, 24	6, 1, 32	3, 6, 32		3, 6, 32	26, 32, 27	10, 16, 31, 28		24, 34, 28, 32	2, 6, 32
29	Manufacturing precision	3, 27	3, 27, 40		19, 26	3, 32	32, 2		32, 2	13, 32, 2	35, 31, 10, 24		32, 26, 28, 18	32, 30
30	Object-affected harmful factors	18, 35, 37, 1	22, 15, 33, 28	17, 1, 40, 33	22, 33, 35, 2	1, 19, 32, 13	1, 24, 6, 27	10, 2, 22, 37	19, 22, 31, 2	21, 22, 35, 2	33, 22, 19, 40	22, 10, 2	35, 18, 34	35, 33, 29, 31
31	Object-generated harmful factors	15, 35, 22, 2	15, 22, 33, 31	21, 39, 16, 22	22, 35, 2, 24	19, 24, 39, 32	2, 35, 6	19, 22, 18	2, 35, 18	21, 35, 2, 22	10, 1, 34	10, 21, 29	1, 22	3, 24, 39, 1
32	Ease of manufacture	1, 3, 10, 32	27, 1, 4	35, 16	27, 26, 18	28, 24, 27, 1	28, 26, 27, 1	1, 4	27, 1, 12, 24	19, 35	15, 34, 33	32, 24, 18, 16	35, 28, 34, 4	35, 23, 1, 24
33	Ease of operation	32, 40, 3, 28	29, 3, 8, 25	1, 16, 25	26, 27, 13	13, 17, 1, 24	1, 13, 24		35, 34, 2, 10	2, 19, 13	28, 32, 2, 24	4, 10, 27, 22	4, 28, 10, 34	12, 35
34	Ease of repair	11, 1, 2, 9	11, 29, 28, 27	1	4, 10	15, 1, 13	15, 1, 28, 16		15, 10, 32, 2	15, 1, 32, 19	2, 35, 34, 27		32, 1, 10, 25	2, 28, 10, 25
35	Adaptability or versatility	35, 3, 32, 6	13, 1, 35	2, 16	27, 2, 3, 35	6, 22, 26, 1	19, 35, 29, 13		19, 1, 29	18, 15, 1	15, 10, 2, 13		35, 28	3, 35, 15
36	Device complexity	2, 13, 28	10, 4, 28, 15		2, 17, 13	24, 17, 13	27, 2, 29, 28		20, 19, 30, 34	10, 35, 13, 2	35, 10, 28, 29		6, 29	13, 3, 27, 10
37	Difficulty of detecting and measuring	27, 3, 15, 28	19, 29, 39, 25	25, 34, 6, 35	3, 27, 35, 16	2, 24, 26	35, 38	19, 35, 16	18, 1, 16, 10	35, 3, 15, 19	1, 18, 10, 24	35, 33, 27, 22	18, 28, 32, 9	3, 27, 29, 18
38	Extent of automation	25, 13	6, 9		26, 2, 19	8, 32, 19	2, 32, 13		28, 2, 27	23, 28	35, 10, 18, 5	35, 33	24, 28, 35, 30	35, 13
39	Productivity	29, 28, 10, 18	35, 10, 2, 18	20, 10, 16, 38	35, 21, 28, 10	26, 17, 19, 1	35, 10, 38, 19	1	35, 20, 10	28, 10, 29, 35	28, 10, 35, 23	13, 15, 23		35, 38

#	Improving Parameter	27 Reliability	28 Measurement accuracy	29 Manufacturing precision	30 Object-affected harmful factors	31 Object-generated harmful factors	32 Ease of manufacture	33 Ease of operation	34 Ease of repair	35 Adaptability or versatility	36 Device complexity	37 Difficulty of detecting and measuring	38 Extent of automation	39 Productivity
1	Weight of moving object	1, 3, 11, 27	28, 27, 35, 26	28, 35, 26, 18	22, 21, 18, 27	22, 35, 31, 39	27, 28, 1, 36	35, 3, 2, 24	2, 27, 28, 11	29, 5, 15, 8	26, 30, 36, 34	28, 29, 26, 32	26, 35 18, 19	35, 3, 24, 37
2	Weight of stationary object	10, 28, 8, 3	18, 26, 28	10, 1, 35, 17	2, 19, 22, 37	35, 22, 1, 39	28, 1, 9	6, 13, 1, 32	2, 27, 28, 11	19, 15, 29	1, 10, 26, 39	25, 28, 17, 15	2, 26, 35	1, 28, 15, 35
3	Length of moving object	10, 14, 29, 40	28, 32, 4	10, 28, 29, 37	1, 15, 17, 24	17, 15	1, 29, 17	15, 29, 35, 4	1, 28, 10	14, 15, 1, 16	1, 19, 26, 24	35, 1, 26, 24	17, 24, 26, 16	14, 4, 28, 29
4	Length of stationary object	15, 29, 28	32, 28, 3	2, 32, 10	1, 18		15, 17, 27	2, 25	3	1, 35	1, 26	26		30, 14, 7, 26
5	Area of moving object	29, 9	26, 28, 32, 3	2, 32	22, 33, 28, 1	17, 2, 18, 39	13, 1, 26, 24	15, 17, 13, 16	15, 13, 10, 1	15, 30	14, 1, 13	2, 36, 26, 18	14, 30, 28, 23	10, 26, 34, 2
6	Area of stationary object	32, 35, 40, 4	26, 28, 32, 3	2, 29, 18, 36	27, 2, 39, 35	22, 1, 40	40, 16	16, 4	16	15, 16	1, 18, 36	2, 35, 30, 18	23	10, 15, 17, 7
7	Volume of moving object	14, 1, 40, 11	26, 26, 28	25, 28, 2, 16	22, 21, 27, 35	17, 2, 40, 1	29, 1, 40	15, 13, 30, 12	10	15, 29	26, 1	29, 26, 4	35, 34, 16, 24	10, 6, 2, 34
8	Volume of stationary object	2, 35, 16		35, 10, 25	34, 39, 19, 27	30, 18, 35, 4	35		1		1, 31	2, 17, 26		35, 37, 10, 2
9	Speed	11, 35, 27, 28	28, 32, 1, 24	10, 28, 32, 25	1, 28, 35, 23	2, 24, 35, 21	35, 13, 8, 1	32, 28, 13, 12	34, 2, 28, 27	15, 10, 26	10, 28, 4, 34	3, 34, 27, 16	10, 18	
10	Force (Intensity)	3, 35, 13, 21	35, 10, 23, 24	28, 29, 37, 36	1, 35, 40, 18	13, 3, 36, 24	15, 37, 18, 1	1, 28, 3, 25	15, 1, 11	15, 17, 18, 20	26, 35, 10, 18	36, 37, 10, 19	2, 35	3, 28, 35, 37
11	Stress or pressure	10, 13, 19, 35	6, 28, 25	3, 35	22, 2, 37	2, 33, 27, 18	1, 35, 16	11	2	35	19, 1, 35	2, 36, 37	35, 24	10, 14, 35, 37
12	Shape	10, 40, 16	28, 32, 1	32, 30, 40	22, 1, 2, 35	35, 1	1, 32, 17, 28	32, 15, 26	2, 13, 1	1, 15, 29	16, 29, 1, 28	15, 13, 39	15, 1, 32	17, 26, 34, 10
13	Stability of the object's composition		13	18	35, 24, 30, 18	35, 40, 27, 39	35, 19	32, 35, 30	2, 35, 10, 16	35, 30, 34, 2	2, 35, 22, 26	35, 22, 39, 23	1, 8, 35	23, 35, 40, 3
14	Strength	11, 3	3, 27, 16	3, 27	18, 35, 37, 1	15, 35, 22, 2	11, 3, 10, 32	32, 40, 25, 2	27, 11, 3	15, 3, 32	2, 13, 25, 28	27, 3, 15, 40	15	29, 35, 10, 14
15	Duration of action of moving object	11, 2, 13	3	3, 27, 16, 40	22, 15, 33, 28	21, 39, 16, 22	27, 1, 4	12, 27	29, 10, 27	1, 35, 13	10, 4, 29, 15	19, 29, 39, 35	6, 10	35, 17, 14, 19
16	Duration of action of stationary object	34, 27, 6, 40	10, 26, 24		17, 1, 40, 33	22	35, 10	1	1	2		25, 34, 6, 35	1	20, 10, 16, 38
17	Temperature	19, 35, 3, 10	32, 19, 24	24	22, 33, 35, 2	22, 35, 2, 24	26, 27	26, 27	4, 10, 16	2, 18, 27	2, 17, 16	3, 27, 35, 31	26, 2, 19, 16	15, 28, 35
18	Illumination intensity		11, 15, 32	3, 32	15, 19	35, 19, 32, 39	19, 35, 28, 26	28, 26, 19	15, 17, 13, 16	15, 1, 1, 19	6, 32, 13	32, 15	2, 26, 10	2, 25, 16
19	Use of energy by moving object	19, 21, 11, 27	3, 1, 32		1, 35, 6, 27	2, 35, 6	28, 26, 30	19, 35	1, 15, 17, 28	15, 17, 13, 16	2, 29, 27, 28	35, 38	32, 2	12, 28, 35
20	Use of energy by stationary object	10, 36, 23			10, 2, 22, 37	19, 22, 18	1, 4					19, 35, 16, 25		1, 6
21	Power	19, 24, 26, 31	32, 15, 2	32, 2	19, 22, 31, 2	2, 35, 18	26, 10, 34	26, 35, 10	35, 2, 10, 34	19, 17, 34	20, 19, 30, 34	19, 35, 16	28, 2, 17	28, 35, 34
22	Loss of Energy	11, 10, 35	32		21, 22, 35, 2	21, 35, 2, 22		35, 32, 1	2, 19		7, 23	35, 3, 15, 23	2	28, 10, 29, 35
23	Loss of Substance	10, 29, 39, 35	16, 34, 31, 28	35, 10, 24, 31	33, 22, 30, 40	10, 1, 34, 29	15, 34, 33	32, 28, 2, 24	2, 35, 34, 27	15, 10, 2	35, 10, 28, 24	35, 18, 10, 13	35, 10, 18	28, 35, 10, 23
24	Loss of Information	10, 28, 23			22, 10, 1	10, 21, 22	32	27, 22				35, 33	35	13, 23, 15
25	Loss of Time	10, 30, 4	24, 34, 28, 32	24, 26, 28, 18	35, 18, 34	35, 22, 18, 39	35, 28, 34, 4	4, 28, 10, 34	32, 1, 10	35, 28	6, 29	18, 28, 32, 10	24, 28, 35, 30	
26	Quantity of substance	18, 3, 28, 40	13, 2, 28	33, 30	35, 33, 29, 31	3, 35, 40, 39	29, 1, 35, 27	35, 29, 25, 10	2, 32, 10, 25	15, 3, 29	3, 13, 27, 10	3, 27, 29, 18	8, 35	13, 29, 3, 27
27	Reliability	X	32, 3, 11, 23	11, 32, 1	27, 35, 2, 40	35, 2, 40, 26		27, 17, 40	1, 11	13, 35, 8, 24	13, 35, 1	27, 40, 28	11, 13, 27	1, 35, 29, 38
28	Measurement accuracy	5, 11, 1, 23	X		28, 24, 22, 26	3, 33, 39, 10	6, 35, 25, 18	1, 13, 17, 34	1, 32, 13, 11	13, 35, 2	27, 35, 10, 34	26, 24, 32, 28	28, 2, 10, 34	10, 34, 28, 32
29	Manufacturing precision	11, 32, 1		X	26, 28, 10, 36	4, 17, 34, 26		1, 32, 35, 23	25, 10		26, 2, 18		26, 28, 18, 23	10, 18, 32, 39
30	Object-affected harmful factors	27, 24, 2, 40	28, 33, 23, 26	26, 28, 10, 18	X		24, 35, 2	2, 25, 28, 39	35, 10, 2	35, 11, 22, 31	22, 19, 29, 40	22, 19, 29, 40	33, 3, 34	22, 35, 13, 24
31	Object-generated harmful factors	24, 2, 40, 39	3, 33, 26	4, 17, 34, 26		X					19, 1, 31	2, 21, 27, 1	2	22, 35, 18, 39
32	Ease of manufacture		1, 35, 12, 18		24, 2		X	2, 5, 13, 16	35, 1, 11, 9	2, 13, 15	27, 26, 1	6, 28, 11, 1	8, 28, 1	35, 1, 10, 28
33	Ease of operation	17, 27, 8, 40	25, 13, 2, 34	1, 32, 35, 23	2, 25, 28, 39		2, 5, 12	X	12, 26, 1, 32	15, 34, 1, 16	32, 26, 12, 17		1, 34, 12, 3	15, 1, 28
34	Ease of repair	11, 10, 1, 16	10, 2, 13	25, 10	35, 10, 2, 16		1, 35, 11, 10	1, 12, 26, 15	X	7, 1, 4, 16	35, 1, 13, 11		34, 35, 7, 13	1, 32, 10
35	Adaptability or versatility	35, 13, 8, 24	35, 5, 1, 10		35, 11, 32, 31		1, 13, 31	15, 34, 1, 16	1, 16, 7, 4	X	15, 29, 37, 28	1	27, 34, 35	35, 28, 6, 37
36	Device complexity	13, 35, 1	2, 26, 10, 34	26, 24, 32	22, 19, 29, 40	19, 1	27, 26, 1, 13	27, 9, 26, 24	1, 13	29, 15, 28, 37	X	15, 10, 37, 28	15, 1, 24	12, 17, 28
37	Difficulty of detecting and measuring	27, 40, 28, 8	26, 24, 32, 28		22, 19, 29, 28	2, 21	5, 28, 11, 29	2, 5	12, 26	1, 15	15, 10, 37, 28	X	34, 21	35, 18
38	Extent of automation	11, 27, 32	28, 26, 10, 34	28, 26, 18, 23	2, 33	2	1, 26, 13	1, 12, 34, 3	1, 35, 13	27, 4, 1, 35	15, 24, 10	34, 27, 25	X	5, 12, 35, 26
39	Productivity	1, 35, 10, 38	1, 10, 34, 28	18, 10, 32, 1	22, 35, 13, 24	35, 22, 18, 39	35, 28, 2, 24	1, 28, 7, 10	1, 32, 10, 25	1, 35, 28, 37	12, 17, 28, 24	35, 18, 27, 2	5, 12, 35, 26	X